μR10000 / μR20000
Usage Precautions

## Compatibility with Input Terminals and Option Terminals of Older Models

CAUTION

- The input and option terminals of this instrument are specific to this instrument. Do not connect to the input terminals or option terminals of the μR1000, μR1800, or other models as malfunction can result.

Installing Felt Pens (Pen Models)

CAUTION

- Do not press or pinch the felt tip to prevent deformation.
- Do not move the penholder left or right by force to protect the driving mechanism.

1. Turn ON the power switch and press the [FUNC] key.

2. Press the ▽△ ([DISP]) key several times to display the **Pen exchange** screen.

   ```
   Func=Pen exchange
   ```

3. Press the ⏎ ([CH UP]) key.
   The pen holder moves near the center position, and the **Pen exchange = End** appears.

4. Install the pen.

   μ**R10000**　　　　　　　μ**R20000**

5. Press the ⏎ ([CH UP]) key.
   The screen returns to the data display screen.